Work Order ID 60370 July 6, 2010 2:57:50 PM Page 1 Item ID: D3783-043 Accept Setup Start **Revision ID:** Item Name: Longitudinal Brace Assembly Stop **Start Date:** 7/06/10 Start Qty: 6.00 **Cust Item ID:** Required Date: 7/20/10 Req'd Qty: 6.00 **Customer:** Reference: Run Start Approvals: Process Plan: ____ Date: /0/7/6 Tooling: Date: Date: Stop **SPC (Y/N):** Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. **Work Center ID** Description **Run Hours** Code Qty Qty Number Stamp **Draw Nbr Revision Nbr** D3783 Rev A 100 Pick Kit 0.00 0.00 S 10/07/15 Packaging Memo Packaging 110 0.00 Small Fab Sb 10/07/15 Small Fab 0.00 Memo Small Fab 1-assemble as per dwg D3783 120 QC5- Inspect part completeness to step on W/O 6,010715 QC Memo Quality Control

Dart Aerospace Ltd WORK ORDER CHANGES W/O: **Approval Approval STEP** DATE PROCEDURE CHANGE By Date Qty Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: _____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: ____ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B Verification **Description of NC Approval Approval STEP** DATE Sign & **Action Description** Initial QC Inspector Section A Section C Chief Eng Date Chief Eng Chief Eng

NOTE: Date & initial all entries

Work Order ID 60370

July 6, 2010 2:57:50 PM



Page 2

Item ID:

D3783-043

Accept

Setup Start

Stop



Revision ID: Item Name: **Start Date:**

Longitudinal Brace Assembly

7/06/10

Start Qty: 6.00 Req'd Qty: 6.00

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Required Date: 7/20/10

Process Plan: _____ Date: ____ Tooling:

Date:

Run

Start



Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Sequence ID/ **Work Center ID**

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: 349 A

Memo

0.00

0.00

Tool # Plan

Accept Code Qty

Reject Qty

Reject Number Stamp

Insp.

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

MF 10-7-19

Dart Ae	rospace	e Ltd									
W/O:				WC	ORK ORDER CHAN	GES					
DATE	STEP		PR	OCEDURE CHA	OCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No):		PAR #:	Fault Cate	gory:	NCF	l: Yes	No DQ	A:	Date: _	
	R	esolut	on:	Disposition	n:	QA:	N/C C	losed:		Date: _	
NCR:				WORK ORD	ER NON-CONFORM	IANCE	(NCF	R)			
		2			Corrective Action Se	Section B			cation	Approval	Approva
DATE	STEP		Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	ì	Sign of Date	& Sec	tion C	Approval Chief Eng	QC Inspect
								÷			

NOTE: Date & initial all entries

Comments:

July 6, 2010 2:57:49 PM

Work Order ID: 60370

Parent Item: D3783-043

Parent Item Name: Longitudinal Brace Assembly

Start Date: 7/06/10


Required Date: 7/20/10

Start Qty: 6.00

Required Qty: 6.00

	IPP Rev:B 08-06-	·17 rev.a as per	dwg DE	verified by:	EC				<u> </u>		 		
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN5-13A		Purchased	. No			110	Each	70.0000		6		+ }	
Bolt												•	

Location	Lo	c Oty	Loc Code
ST338		70	
114181		20	
114615		50	
	110	Each	0.0000



AN960JD516 NAS1149D0563J) Purchased Washer D3765-1

Manufactured · No

IPP Rev:A 08-05-19 new issue DD verified by:ec

H113706 110 Each 11.0000

			1
. 6	So	10/07	15 b

Clevis

Manufactured

Location	<u>Lo</u>	c Qty	Loc Code
ST250		11	
56421		11	
	110	Each	0.0000
		^ -	

6	S	10/07/156
---	---	-----------

D3769-3 Tube MS21042L5

Purchased No 110 463.0000

Sh 10/07 6


Nut

Location Loc Qty Loc Code ST139 463 114813 463

Sp 10/04/15 6

Dart Ae	rospace L	_td							
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
Part No):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	Res	solution:	Disposition	n:	QA: N/C (Closed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NC	R)			•
		Description of NC	tion of NC Corrective Action			Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sect	ion C	Chief Eng	QC Inspecto
						·			
				· · · · · · · · · · · · · · · · · · ·					
				and the second s					
		1							

NOTE: Date & initial all entries



08.06.04


DATE

SCALE

COPYRIGHT © 2008 BY DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL MODE IS UPPLIED ON THE EMPRISE CONDITION THAT IT IS,
HOT TO BE USED FOR ANY PURPOSE ON COMED ON COMMUNICATED TO ANY OTHER RESIDENTIAL MODE

NTS



NOTES:	
1) MATERIAL: N/A	
2) FINISH: N/A	
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NO	ED
4) UNITS: INCHES UNLESS OTHERWISE NOTED	
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX	
6) IDENTIFICATION: N/A	
7) WEIGHT: 0.41 lbs	

DESIGN	HS	DART AEROSPACE	ITD			
DRAWN	HS	HAWKESBURY, ONTARIO, CAN				
CHECKED	RH	DRAWING NO.	REV. A			
MFG, APPR.	(74)	D3783	SHEET 2 OF 3			
APPROVED	M	TITLE	SCALE			
DE APPR.	7	BRACE ASSEMBLY	NTS			
DATE 08.0	6.04	COPYRIGHT © 2008 BY DART AEROSPACE LTD THE BOCHMENT E PRIVATE AND CONFIDENTIAL AND IS EMPT AED ON THE EMPT AES CONSIDER THAT IT IS NOT TO BE USED FOR ANY PUMPOSE OF COMMUNICATION TO THE OTHER PERSON WITHOUT WITH THE PERMISSION FROM DIAT REPORTED.				



DRAWING NO. CHECKED REV. A MFG. APPR. SHEET 3 OF 3 APPROVED TITLE SCALE DE APPR. BRACE ASSEMBLY

DATE 08.06.04

NTS COPYRIGHT 0 2008 BY DART AEROSPACE LTD
THIS OCCUMENT IS FRANTE AND CONFIDENTIAL AND IS SUPPLIED OF THE EXPRESS CONSTITUTION OF THE PROPRIED ON COMMUNICATION TO ANY DEVELOPMENT OF THE PROPRIED ON COMMUNICATION TO ANY OTHER PROPRIED.